Lexmark 40X8507 fuser

Brand: Lexmark Product code: 40X8507

Product name: 40X8507

Fuser Type 19, 220-240V

Lexmark 40X8507 fuser:

The operator panel displays the message 80 "Replace maintenance kit" at required maintenance intervals. You must replace the fuser, transfer roller, pick roller, and separation roller at this interval to maintain the print quality and reliability of the printer.

Check the 2 digit type code on the fuser, or check Device Information using the embedded web server or the menus page for a replacement part number.

There are multiple warnings to indicate that the fuser is nearing end of life and that a maintenance kit is required, including error codes 80.0x, 80.1x, and 80.2x. If you receive error code 80.3x, the fuser has reached its rated life and the printer stops until a maintenance kit is installed. You must install the correct Fuser Maintenance Kit for the type of fuser that is installed in the printer.

Lexmark 40X8507. Brand compatibility: Lexmark, Compatibility: MS710dn MS711dn. Quantity per pack: 1 pc(s)

Features		Packaging data	
Brand compatibility	Lexmark	Quantity per pack	1 pc(s)
Compatibility	MS710dn MS711dn		

