Item Number

RAM No-Drill™ Seat Bases

RAM-VB-103 & RAM-VB-103-SW1

RAM Mounting Systems

Vehicle base for the

Chevrolet 1500 C/K - 2wd (1994-1999)

Chevrolet 1500 C/K - 4wd-selector on dash only (1994-1999)

Chevrolet 2500 C/K (1994-1999)

Chevrolet 3500 C/K (1994-1999) Chevrolet Blazer K-5 (1993-Older) Chevrolet Suburban (1994-1999) Chevrolet Tahoe (1994-1999) GMC Sierra (1994-1999) GMC Yukon (1994-1999)

Chevrolet Silverado (1998-Older)

SPECIFICATIONS

Placement

Across Transmission Hump

Drilling Required

No - uses existing seat bolts on all vehicles Except full size Blazer. Drilling is required for this vehicle 1993 and older

Seat Configuration

Bucket/Bench

Construction/Finish

Steel/Black Powdercoat

Dimensions

A = 14.5", B = 3.75", C = 5.5", D = 9.5", E = 6.25" Hole Center = 23.13"

Pole or Pedestal

Ordered Separately

Weight

6.4 lbs.

A Vehicle Base

RAM-VB-103

Complete Vehicle Mount

RAM-VB-103-SW1

Notes.

This base may not work with the factory installed center console or with 4WD levers that are on the floor. Drilling may be required for vehicles with a bench seat. Some models have factory installed accessories that prevent installation. This base is designed to be installed over the transmission hump.

RAM Mounting Systems

8410 Dallas Ave S Seattle, WA 98108 Phone: (206) 763-8361 Fax: (206) 763-9615 www.rammount.com support@rammount.com



RMR-INS-VB-103

Item Number

RAM No-Drill TM Seat Bases

RAM-VB-103 & RAM-VB-103-SW1

RAM Mounting Systems

Vehicle base for the

Chevrolet 1500 C/K - 2wd (1994-1999)

Chevrolet 1500 C/K - 4wd-selector on dash only (1994-

1999)

Chevrolet 2500 C/K (1994-1999)


Chevrolet 3500 C/K (1994-1999)

Chevrolet Blazer K-5 (1993-Older)

Chevrolet Silverado (1998-Older) Chevrolet Suburban (1994-1999) Chevrolet Tahoe (1994-1999) GMC Sierra (1994-1999) GMC Yukon (1994-1999)

INSTALLATION INSTRUCTIONS

- 1. Place both front seats in their most rear position.
- 2. Remove the drivers side front right and the passenger side front left seat mounting bolts (inner seat bolts).
- 3. Slightly lift both the passenger and driver seats and slide the No-Drill™ base between the floor of the vehicle and the bottom of the seat.
- 4. Align the holes and reinstall all of the seat bolts that have been removed.



RAM Mounting Systems

8410 Dallas Ave S Seattle, WA 98108 Phone: (206) 763-8361 Fax: (206) 763-9615 www.rammount.com support@rammount.com



RMR-INS-VB-103